# ELEXON

## Circular

| | | | |
|---|---|---|---|
| Type and number | **MDD Circular 00728** | | |
| Date and time | **11 February 2021** | Purpose | **For Information** |
| To | **Market Participants** | From | **MDD Co-ordinator** |

### Clock Interval Error in Market Domain Data (MDD) Version 307

Elexon has identified an invalid Clock Interval entry in MDD Version 307 which might need manually removing by Participants. See MDD Circular 00724 for more information on the original issue.

The Clock Interval with the correct End Month of '5' was included in MDD Version 307, but the incorrect Clock Interval was not removed. This is causing duplicate time periods for TPR 00524. This might cause issues for Participants loading the D0269 or D0270 files.

Elexon will correct this in MDD Version 308 with a go-live date of 17 March 2021. Until this is rectified, you might need to make the following manual amendment before loading the D0269 or D0270 files into your systems.

**Please remove the Clock Interval below for TPR 00524 only;**

| Time Pattern Regime ID | Day of the Week ID | Start Day | Start Month | End Day | End Month | Start Time | End Time |
|---|---|---|---|---|---|---|---|
| 524 | 5 | 1 | 1 | 31 | 12 | 22:30 | 23:30 |

**Incorrect line in D0269/D0270 file for removal:**

`CKI|5|31|12|233000|1|1|223000`

The above Clock Interval also exists for another TPR so please ensure that you remove the record from the TPD 00524 group only.

If you have any questions or concerns, please email the BSC Service Desk bscservicedesk@cgi.com and copy in the MDD Mailbox mddc@elexon.co.uk

Freya Gardner

Elexon, Digital Operations