This process details the process for disconnecting a redundant MSID as required under P434 \sim 10 10 10 (183) Notify UMSO of Receive & process Receive & process UMSO De-energisation MSID to confirmation of confirmation of & Disconnection disconnected disconnection disconnection Supplier D0171 Email D0125 UMSO SMRA LDSO

UMSO – Disconnection (P434)

